

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



AOL
Notes

Looking AOL



Profile right Bol
Notes

None

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



GirderB6 span 5 LT

Notes

Girder bent 6 span 5 left, note a large rock hammer fits in the gap caused by titled bearing/broke/bent end of girder. see next pic for close up of broken area just above bottom flange to the bearing stiffener.



Girder end b6 left

Notes

Bent 6 span 5 left girder end same area as last photo. this area was only bent in 2009 inspection.

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



2009 photo b6 girder

Notes

This a photo of bent6 span5 left girder from 2009 note amount of gap between bearing and bottom of girder compaired to 2011 inspection.
Also note web near bottom flange at end of girder is only bent 2009 , broken 2011.



2009 b6 left girder

Notes

Another view of bent 6 span 5 end left girder from 2009.

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



Joint bent 5

Notes

Spalling around joint at bent 5.



Girder B4 Left

Notes

Girder at bent 4 left span 3 side web. Paint loss rust,no section loss yet. Typical at bents.

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



Stringer B4

Notes

Stringer bent 4 number 1 left. 3/32" section loss in web. 2009 just a start of section loss.



Bearing B6 RT

Notes

Bearings bent 6 right, spans 5 and 6.

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



Bearing B4 RT

Notes

None



Under deck

Notes

Under deck at bent 6 looking BOL.

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



Under deck span6

Notes

Under deck span 6 looking AOL.



Abutment cap B1

Notes

Abutment at bent 1, left, cap looking BOL. Material on cap. Typical all 4 corners of bridge.

Inspection Photos

I00090053+07232

Location 10 KM E SUPERIOR Stucture Name: none



Bearings B7 Lt

Notes

Bearings bent 7 left side. Span 6 and 7. Typical of bearings at bent 7.



Bent 3 cap

Notes

Bent 3 cap span 2 side note areas of delamination.